## STORMWATER ANNUAL REPORT - METAL MINING (& COAL) COLORADO DEPT. OF PUBLIC HEALTH & ENVIRONMENT

Received Water Quality Control Division WOCD-P-B2 4300 Cherry Creek Drive South Water Quality Control Denver, Colorado 80246-1530 Make enough copies of form for each reporting year. Or go to www.cdphe.state.co.us/wq/PermitsUnit Check if this is a Permittee (Company Name): Sunnyside Gold Corporation Facility Name: Mayflower Mill Mailing Address: PO Box 177, Silverton, CO 81433 Facility Phone Number: none Permit Certification No. COR-04 0 0 5 4 THIS IS A REQUIRED FIELD If this is not filled in the report will be returned. - Please do not input "0000" 1 5 Reporting Period: Jan. 1-Dec. 31, 20 (Form is due by Feb. 15 of the following year) \*\*Each section must be completed. Please print or type.\*\* A. A report on the facility's overall compliance with the SWMP. (Include here a summary of any measures taken to comply with your Stormwater Management Plan (SWMP), to fully implement it, changes or improvements made in any of your Best Management Practices (BMPs), employee training, spills, other problems encountered, etc. How is your plan working?) This facility is in final reclamation. No materials were on-site. The remaining task for completion is the establishment of sufficient vegetation to meet the post-mining land use. No problems were noted during inspections. Were changes made to your SWMP? No Yes - Describe changes on a separate sheet. B. A summary of each comprehensive stormwater facility inspection made, including date, findings, and action <u>taken</u>. (The permit requires at least **two** comprehensive facility inspections per year - see page 12 of the permit. Include here a summary of those inspections, plus any other comprehensive inspections made. It is not necessary to summarize day-to-day inspections, unless significant problems were noted.) First Inspection - Date 05-01-2015 . Findings, and action taken:

Small flows were observed in some of the diversion ditches. Flows were clear of sediments. No signs of erosion were found. No materials were on-site. Vegetation is improving. No maintenance action required.

## STORMWATER ANNUAL REPORT - METAL MINING (& COAL) Permit Cert. No. COR-04 0 0 5 4

Second Inspection – Date 09-09-2015	Findings, and action taken:
There were no flows and no problems	were found. No material is stored on-site. Vegetation was looking good.
Other Inspections - Date	Findings, and action taken:
¥	
results. (Monitoring is not a requir	ormwater monitoring performed. Attach a separate sheet with the lab ement under the permit, unless you were specifically directed to do so by of any stormwater monitoring that you performed on your own should be
Monitoring Results Attached? ☑ 1	No Yes
. Certification	
supervision in accordance with a sy evaluate the information submitted. those persons directly responsible f knowledge and belief, true, accurate	this document and all attachments were prepared under my direction or stem designed to assure that qualified personnel properly gather and Based on my inquiry of the person or persons who manage the system, or gathering the information, the information submitted is, to the best of the e, and complete. I am aware that there are significant penalties for ling the possibility of fine and imprisonment for knowing violations."
Lany Pein	02-05-2016
Signature of Permittee (legally resp	onsible person) Date Signed
Larry Perino	Reclamation Manager
Name (printed)	Title
se additional pages as needed.	Page 2 of 2 ar6/06